

In this module you will need to setup lists for **Device Types** and **Locations** where measuring devices will be used or stored. These settings will be loaded into drop-down lookup lists in various data entry forms.

	Size	Location	Calib Date	Next Due ...	Status
		QC Lab	4/14/2008	4/15/2009	ACTIVE
meter	1000V	QC Lab	6/12/2008	12/13/2008	ACTIVE

Setup Measuring Device Types

No	Type of measuring Device		
1	Caliper		
2	Dial Indicator		
3	Digital Multimeter	<input type="checkbox"/>	<input type="checkbox"/>
4	Oscilloscope	<input type="checkbox"/>	<input type="checkbox"/>
5	Flow Meter	<input type="checkbox"/>	<input type="checkbox"/>
*		<input type="checkbox"/>	<input type="checkbox"/>

OK Cancel Apply

Both setup forms are based on the standard 'Categories' form. The use of this type of form is explained in tutorial **Navigation and Common Features - Category Setups**.

ISOX PRESS

Setups

- Device Types
- Locations

Modules

- Doc Menu
- Doc Control
- Corrective Action
- Internal Audits
- Mngmnt Review
- Training
- NC Product
- Supplier Control
- Cust. Complaints
- Measuring Devices

End of Slide Show. Thank You for Watching